


Figure shows details of Machine Vice. Assemble the parts and draw the following views:-
 (a) Sectional front view (b) Top view



Sol.

